

AutoCAD shortcuts & hotkey guide

Toggles and Screen Management

Toggle General Features	
Ctrl+E	Toggle coordinate display
Ctrl+G	Toggle Grid
Ctrl+E	Cycle isometric planes
Ctrl+F	Toggle running object snaps
Ctrl+H	Toggle Pick Style
Ctrl+Shift+H	Toggle Hide palettes
Ctrl+I	Toggle Coords
Ctrl+Shift+I	Toggle Infer Constraints

Manage Screen	
Ctrl+0 (zero)	Clean Screen
Ctrl+1	Property Palette
Ctrl+2	Design Centre Palette
Ctrl+3	Tool Palette
Ctrl+4	Sheet Set Palette
Ctrl+6	DBConnect Manager
Ctrl+7	Markup Set Manager Palette
Ctrl+8	Quick Calc
Ctrl+9	Command Line

Manage Drawings	
Ctrl+N	New Drawing
Ctrl+S	Save drawing
Ctrl+O	Open drawing
Ctrl+P	Plot dialog box
Ctrl+Tab	Switch to next
Ctrl+Shift+Tab	Switch to previous drawing
Ctrl+Page Up	Switch to previous tab in current drawing
Ctrl+Page Down	Switch to next tab in current drawing
Ctrl+Q	Exit
Ctrl+A	Select all objects

Toggle Drawing Modes	
F1	Display Help
F2	Toggle text screen
F3	Toggle object snap mode
F4	Toggle 3DOsnap
F5	Toggle Isoplane
F6	Toggle Dynamic UCS
F7	Toggle grid mode
F8	Toggle ortho mode
F9	Toggle snap mode
F10	Toggle polar mode
F11	Toggle object snap tracking
F12	Toggle dynamic input mode

Manage Workflow	
Ctrl+C	Copy object
Ctrl+X	Cut object
Ctrl+V	Paste object
Ctrl+Shift+C	Copy to clipboard with base point
Ctrl+Shift+V	Paste data as block
Ctrl+Z	Undo last action
Ctrl+Y	Redo last action
Ctrl+[Cancel current command (or ctrl+\)
ESC	Cancel current command



Click Below to Download More Articles

<https://techguruplus.com/blog/>